



Dart Hawkesbury
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D3773-041
Job Sheet 168554



Part No: D3773-041

Job Qty: 3 ea

Part Name: Headrest Assembly



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 11/16/17

Job Tracking No:

Due Date: 11/24/17

Created By: Mario Poulin

Type: Stock

Description:

Note: DWG REV B IPP Rev:A 08-05-21 new issue DD verified by:ec IPP Rev:B 08-07-18 revB as per dwg DD verified by:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	3 Ea		11/23/17	0.00	0.00	Start Up Large Fab-1		<i>JS</i>
110	Large Fab	3 pcs		11/24/17	0.00	1.25	Large Fab 2		<i>JS</i>
120	QC	3 pcs		11/24/17	0.00	0.00	QC5		<i>PD 17.12.04</i>
130	QC	3 pcs		11/24/17	0.00	0.00	QC9		<i>PD 17.12.04</i>
140	Packaging	3 pcs		11/24/17	0.00	0.00	Packaging3	<i>57252</i>	<i>SY</i>
150	QC21-SA	3 Ea		11/24/17	0.00	0.00	QC21		<i>2-20</i>

DEC 06 2017

Job Allocations

Operation	Component Part	Required	Inventory	Allocated	Std Qty
90-Start up Operation	D3773-1	3	3	0	0
	D3773-3	3	6	0	0

Part Specifications


Specifications could not be found.

Plex 11/16/17 4:58 PM dart.poulin.mario

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____
QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____ Date: _____		DISPOSITION ☐ Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved		AGAINST DEPARTMENT/PROCESS ☐ Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ QTY Effect		☐ Engineering ☐ Water Jet ☐ Approval																																																																																																									
DART AEROSPACE S010839  Headrest Assembly				Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K64 1K7 CANADA TEL.: 1 613 632-5200 Email: sales@dartaero.com www.dartaerospace.com																																																																																																											
PART NO: D3773-041 Revision: Operation: Start up Operation Change No:				Mfg Date: 11/17/17 Job No: 168554																																																																																																											
Description Work Order Deviation																																																																																																															
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="4" style="text-align: left;">Root Cause</th> <th colspan="4" style="text-align: left;">OTHER :</th> </tr> <tr> <td style="width:10%;">Environment</td> <td style="width:10%;">No Re-verification</td> <td style="width:10%;">Pressure/Forced</td> <td style="width:10%;">Temperature/Cure</td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> </tr> <tr> <td>Design</td> <td>Operator</td> <td>Bending</td> <td>Set-up</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Doc/Data</td> <td>Offset/Setup</td> <td>Centre Not Concentric</td> <td>BOM/Route</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Equip/Tooling</td> <td>Supplier</td> <td>Cracks</td> <td>Broken/Damage/D</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Handling/Pre</td> <td>Training</td> <td>Crimp/Kink/Ripple/Wave</td> <td>Inspection Incomp</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Material</td> <td>Use for Testing</td> <td>Cuffs</td> <td>Contamination</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Internal Transport</td> <td>Poor Information</td> <td>Crushing</td> <td>Countersink</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Tribal Knowledge</td> <td>Rushing</td> <td>Heat Treat</td> <td>Cut Too Short</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>LOA</td> <td>Product Improvement</td> <td>Wave/Twist in Tube</td> <td>Instructions Incom</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Substation</td> <td>Process Improvement</td> <td>Marks/Chatter</td> <td>Drill Holes</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Past Expiry Date</td> <td>Manufacturing Process</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Misidentified</td> <td>Past Due</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>								Root Cause				OTHER :				Environment	No Re-verification	Pressure/Forced	Temperature/Cure					Design	Operator	Bending	Set-up					Doc/Data	Offset/Setup	Centre Not Concentric	BOM/Route					Equip/Tooling	Supplier	Cracks	Broken/Damage/D					Handling/Pre	Training	Crimp/Kink/Ripple/Wave	Inspection Incomp					Material	Use for Testing	Cuffs	Contamination					Internal Transport	Poor Information	Crushing	Countersink					Tribal Knowledge	Rushing	Heat Treat	Cut Too Short					LOA	Product Improvement	Wave/Twist in Tube	Instructions Incom					Substation	Process Improvement	Marks/Chatter	Drill Holes					Past Expiry Date	Manufacturing Process							Misidentified	Past Due						
Root Cause				OTHER :																																																																																																											
Environment	No Re-verification	Pressure/Forced	Temperature/Cure																																																																																																												
Design	Operator	Bending	Set-up																																																																																																												
Doc/Data	Offset/Setup	Centre Not Concentric	BOM/Route																																																																																																												
Equip/Tooling	Supplier	Cracks	Broken/Damage/D																																																																																																												
Handling/Pre	Training	Crimp/Kink/Ripple/Wave	Inspection Incomp																																																																																																												
Material	Use for Testing	Cuffs	Contamination																																																																																																												
Internal Transport	Poor Information	Crushing	Countersink																																																																																																												
Tribal Knowledge	Rushing	Heat Treat	Cut Too Short																																																																																																												
LOA	Product Improvement	Wave/Twist in Tube	Instructions Incom																																																																																																												
Substation	Process Improvement	Marks/Chatter	Drill Holes																																																																																																												
Past Expiry Date	Manufacturing Process																																																																																																														
Misidentified	Past Due																																																																																																														